

Correct as at 5th June 2026. It may be superseded at any time.

Extract taken from: Entry certification > Reference materials > Examples of major structural damage and corrosion > Distortion to longitudinal rails: front and rear crush zones

## 71-7 Distortion to longitudinal rails: front and rear crush zones





Page amended 28 April 2014 (see [amendment details](#)).