

Correct as at 26th June 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of major structural damage and corrosion > Distortion to longitudinal rails: front and rear crush zones

5-7 Distortion to longitudinal rails: front and rear crush zones

Distortion to longitudinal rails: front and rear crush zones



