


Correct as at 26th June 2026. It may be superseded at any time.


Extract taken from: Entry certification > Reference materials > Examples of major structural damage and corrosion > Corrosion which has resulted in perforation or flaking of the metal: Nissan Terrano and Mistral

71-10 Corrosion which has resulted in perforation or flaking of the metal: Nissan Terrano and Mistral

When inspecting Nissan Terranos or Mistrals always check for corrosion of the floor under the rear seat (examples are shown in the first three photos below).









Page amended 28 April 2014 (see [amendment details](#)).