

Correct as at 26th April 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of major structural damage and corrosion > Corrosion which has resulted in perforation or flaking of the metal: Nissan Terrano and Mistral

5-10 Corrosion which has resulted in perforation or flaking of the metal: Nissan Terrano and Mistral

When inspecting Nissan Terranos or Mistrals always check for corrosion of the floor under the rear seat (examples are shown in the first three photos below).







