

VIN photo for Repair certification – unable to enter notes form

From 16 March 2026, you'll need to upload a photo of the vehicle's VIN or chassis number when completing a *Repair certification – unable to enter notes form*.

This will ensure the vehicle details are captured correctly. The online form will be updated to include this function.

nzta.govt.nz/repair-notes