

Correct as at 23rd May 2026. It may be superseded at any time.

Extract taken from: Light vehicle repair certification > Vehicle structure > Plastic repair

2-7 Plastic repair

Reasons for rejection

1. In the absence of specific permission in the manufacturer's instructions, one of the following components has been repaired:

- a) fuel tank or line
- b) structural composite parts and components
- c) energy absorbing bumper
- d) composite leaf spring.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Frontal Impact 2001](#)
- [Land Transport Rule: Vehicle Repair 1998.](#)