

Correct as at 21st April 2026. It may be superseded at any time.

Extract taken from: Entry certification > Inspection and certification > Steering and suspension > PSV steering (heavy PSV)

9-2 PSV steering (heavy PSV)

Reasons for rejection

Prohibited equipment

1. A vehicle entering service as a PSV has its steering column to the left of the longitudinal centreline of the body of the vehicle.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Passenger Service Vehicles 1999](#)

Prohibited equipment

1. A left-hand drive vehicle may not enter service as a PSV.

Page added 1 October 2012 (see [amendment details](#)).