

Correct as at 7th June 2026. It may be superseded at any time.

Extract taken from: In-service certification (WoF and CoF) > Forklifts > Vehicle interior > Interior impact

## 7-7 Interior impact

### Reasons for rejection

#### Condition and performance

1. Where an interior fitting, control or surface has been modified or has deteriorated, the likelihood of injury to occupants has not been minimised.

### Summary of legislation

#### Applicable legislation

- [Land Transport Rule: Interior Impact 2001](#).

#### Condition and performance

1. Interior fittings, controls and surfaces in the passenger compartments must be such that the likelihood of injury to occupants is minimised.