

Correct as at 5th June 2026. It may be superseded at any time.

Extract taken from: Entry certification > Inspection and certification > Lighting > Side-marker lamps (heavy vehicles)

4-8 Side-marker lamps (heavy vehicles)

Reasons for rejection

Mandatory requirements

1. A vehicle does not comply with a requirement relating to permitted equipment set out in the [VIRM: In-service certification, section 4-8](#)

Compliance with approved standards

2. A side-marker lamp that is required to comply with an approved side-marker lamp standard does not comply, or cannot be demonstrated to comply, with at least one of the standards listed in Table 4-8-1

Condition and performance

3. A side-marker lamp does not comply with a requirement relating to condition and performance set out in the [VIRM: In-service certification, section 4-8](#)

Table 4-8-1. Approved side-marker lamp standards*

UN-ECE Regulation no.	EEC/EC Directive	FMVSS	ADR	Japan
91	76/758	108	45 or, 74	JIS D5500 TS for side-marker lamps

* A side-marker lamp that is required to comply with an approved side-marker standard must comply with at least one of the standards listed in the table.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Vehicle Lighting 2004](#)

Permitted equipment

1. Vehicles must comply with the requirements relating to permitted equipment set out in the [VIRM: In-service certification, section 4-8](#).

Compliance with approved standards

2. Side-marker lamps fitted to the following vehicles must comply with one or more of the approved end-outline marker standards in Table 4-8-1:

- vehicles of Class MD3, MD4, ME, NB, NC, TC and TD manufactured on or after 1 January 2006.

Condition and performance

3. Side-marker lamps must comply with the requirements relating to condition and performance set out in the [VIRM: In-service certification, section 4-8](#).