

Correct as at 25th June 2026. It may be superseded at any time.

Extract taken from: Entry certification > Inspection and certification > Lighting > Heavy PSV interior lighting

4-17 Heavy PSV interior lighting

Reasons for rejection

Mandatory requirements

1. A doorway, aisle or set of steps is not adequately illuminated by interior lighting.
2. An interior light interferes with the driver's vision when the doors are closed.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Passenger Service Vehicles 1999](#)

Mandatory requirements

1. Interior lights must be positioned so that they adequately illuminate doorways, aisles and steps, but without interfering with the driver's vision when the doors are closed.