

1 June 2018 (WoF only)

VIRM: In-service certification (WoF only) amendment

– effective 1 June 2018

Section	Change description
Introduction	
3-6 Checksheets	<ul style="list-style-type: none"> • Link to new section 3-11 added
3-9 Collecting fees	<ul style="list-style-type: none"> • Link to new section 3-11 added
3-11 Rechecks	<ul style="list-style-type: none"> • New section putting the recheck and reinspection information in one place
General vehicles	
1-1 VIN and chassis number	<ul style="list-style-type: none"> • What to do if a VIN/chassis number is missing or unreadable.
4-1 Headlamps	<ul style="list-style-type: none"> • New reason for rejection added to mirror summary of legislation 22 that a headlamp must be fitted with a light source that is specified by the vehicle manufacturer or the headlamp manufacturer.
7-1 seats and seat anchorages	<ul style="list-style-type: none"> • Note 20 from the Seatbelts and seatbelt anchorages section added as Note 6.
Motorcycles	
1-1 VIN and chassis number	<ul style="list-style-type: none"> • What to do if a VIN/chassis number is missing or unreadable.
4-1 Headlamps	<ul style="list-style-type: none"> • New reason for rejection added to mirror summary of legislation 20 that a headlamp must be fitted with a light source that is specified by the vehicle manufacturer or the headlamp manufacturer.