

New failure codes for Cardan shaft park brakes

In line with updates to the stall test procedure, new codes were introduced in December 2021 to record when and why a vehicle with a Cardan shaft brake failed its park brake test. All vehicle inspectors should now be using these codes. This data will be very useful to Waka Kotahi and wider industry going forward.

Vehicle or Audit Faults				
Vehicle ▼				
Scroll Next ▼				
Mnt	Fault Code	Type	Description	Category
<input type="checkbox"/>	BQA1	C	CSB ALIGNMENT ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQB1	C	CSB BENT ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQG1	C	CSB CONTAMINATED ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQI1	C	CSB TO IMPROVE ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQJ1	C	CSB REPLACE ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQN1	C	CSB CORROSION ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQO1	C	CSB TO OPERATE ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQU1	C	CSB LOOSE ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQW1	C	CSB WORN ALL	<input type="checkbox"/>
<input type="checkbox"/>	BQY1	C	CSB TO COMPLY ALL	<input type="checkbox"/>