

Correct as at 7th June 2026. It may be superseded at any time.

Extract taken from: In-service certification (WoF and CoF) > Heavy PSVs > Vision > PSV demisters

5-6 PSV demisters

Reasons for rejection

Mandatory equipment

1. The windscreen **and** side window used by the driver is not equipped with demisting equipment.

Condition and performance

2. The demisting equipment:

- a) does not operate, or
- b) is ineffective, eg the air is not hot enough or there is insufficient volume, or
- c) cannot be operated from the driver's seat.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Passenger Service Vehicles 1999](#).

Mandatory equipment

1. The front windscreen and side windows used by the driver must be equipped with effective demisting equipment, adjustable from the driver's seat.