

Correct as at 24th April 2026. It may be superseded at any time.

Extract taken from: Light vehicle repair certification > Vehicle measurement > Four-wheel alignment measurement

8-2 Four-wheel alignment measurement

Reasons for rejection

1. A four-wheel alignment has not been completed when:
 - a) corrosion has affected a steering or suspension attachment, or
 - b) other damage has affected steering or suspension.
2. The measurements of the vehicle are not within the specified tolerance.
3. The measurements have not been taken by a technician approved by the repair certifier.
4. The four-wheel alignment machine is not currently calibrated.

Note 1

A copy of the wheel alignment report must be retained by the repair certifier with the vehicle file.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Vehicle Repair 1998](#).