

10 April 2017

## VIRM: Light vehicle repair certification update – effective 10 April 2017

### List of changes

To view the changes in one document download the [List of changes and preview](#) pages.

Section	Change description
<a href="#">Technical bulletin 5: Threshold for lifting border damage flag</a>	<ul style="list-style-type: none"> <li>• Text added to clarify that cosmetic damage from hail/vandalism is not considered structural damage, even if over multiple panels.</li> </ul>
<a href="#">Technical bulletin 6: LT307 standard operating procedure</a>	<ul style="list-style-type: none"> <li>• Added: <b>Note:</b> the LT307 cannot be used if the vehicles' documentation includes the words 'statutory', 'write-off', 'salvage', 'junked' or 'non-repairable'. An LT308 must be used for any of those cases.</li> <li>• Amended: To issue an LT307 the certifier must first determine that <b>no structural remedial work is required</b> to the entire vehicle.</li> </ul>
<a href="#">Technical bulletin 7: Certification of vehicles written off for hail/malicious/vandalism damage</a>	<ul style="list-style-type: none"> <li>• New bulletin.</li> </ul>