

Correct as at 3rd May 2026. It may be superseded at any time.

Extract taken from: Light vehicle repair certification > Vehicle structure > Points of attachment

2-8 Points of attachment

Reasons for rejection

1. A structure which is used as a point of attachment (Note 1) does not provide a secure mounting (Note 2).

Note 1

A point of attachment is the structure where legally required components such as headlamps, rear-view mirrors, etc are fitted.

Note 2

See [Technical bulletin 1](#) for further information regarding corrosion in Nissan Terrano or Mistral rear floor pan assemblies.

Summary of legislation

Applicable legislation

- [Land Transport Rule: Vehicle Repair 1998](#).