

Amendment details

Amendment date	Reasons for amendment	Amendment details
23 June 2021	<p>A minor change has been made to Technical bulletin 3: Vehicles fitted with ITS Connect regarding how information about vehicles fitted with ITS-Connect is recorded.</p> <p>The change is to clarify where notes are to be recorded for vehicles not fitted with ITS-connect. You should record notes in the BIO's vehicle file, not BIS.</p>	<ul style="list-style-type: none"> • Technical bulletin 3: Vehicles fitted with ITS Connect
1 April 2021	<p>New technical bulletin that defines the process for identifying vehicles fitted with ITS Connect systems and how these vehicles need to be processed if an ITS Connect system is fitted.</p>	<ul style="list-style-type: none"> • Technical bulletin 3: Vehicles fitted with ITS Connect
26 September 2018	<ul style="list-style-type: none"> • New Technical bulletin regarding Takata non-alpha airbags and the process that will be in place from 1 November 2018. • Technical bulletin 1 renamed Takata alpha airbag recall. 	<ul style="list-style-type: none"> • Technical bulletin 1: Takata alpha airbag recall • Technical bulletin 2: Takata non-alpha airbag recall
16 May 2018	<p>Amended page and new technical bulletin regarding the process around the Takata Alpha airbag recall</p>	<ul style="list-style-type: none"> • The border inspection process
3 June 2014	<ul style="list-style-type: none"> • Transition from PDF to inspection portal format • New checksheet for outside NZ inspections • Updated sticker and labeling instructions • Updates to Border inspection system guidelines • Other general items. 	<ul style="list-style-type: none"> • List of changes (PDF)