

Correct as at 25th June 2026. It may be superseded at any time.

**Extract taken from:** Entry certification > Inspection and certification > Steering and suspension > PSV steering (light PSV)

## 9-2 PSV steering (light PSV)

### Reasons for rejection

#### Prohibited equipment

1. A vehicle entering service as a PSV has its steering column to the left of the longitudinal centreline of the body of the vehicle.

### Summary of legislation

#### Applicable legislation

- [Land Transport Rule: Passenger Service Vehicles 1999](#)

#### Prohibited equipment

1. A left-hand drive vehicle may not enter service as a PSV.

Page added 1 October 2012 (see [amendment details](#)).