

Correct as at 5th June 2026. It may be superseded at any time.

Extract taken from: Entry certification > Inspection and certification > Lighting > Cornering lamps

## 4-3 Cornering lamps

### Reasons for rejection

#### Permitted equipment

1. A vehicle does not comply with a requirement relating to permitted equipment set out in the [VIRM: In-service certification, section 4-3](#)

#### Condition and performance

2. A cornering lamp does not comply with a requirement relating to condition or performance set out in the [VIRM: In-service certification, section 4-3](#)

### Summary of legislation

#### Applicable legislation

- [Land Transport Rule: Vehicle Lighting 2004](#)

#### Permitted equipment

1. Vehicles must comply with the requirements relating to permitted equipment set out in the [VIRM: In-service certification, section 4-3](#)

#### Condition and performance

2. Cornering lamps must comply with the requirements relating to condition and performance set out in the [VIRM: In-service certification, section 4-3](#)