

Look out for unusual VIN plates

Fifty blank VIN plates have been stolen from a vehicle inspection site in Whangarei. Please keep an eye out for incorrect style or misaligned stamping on VIN plates.

If you notice anything unusual, please follow the relevant reasons for rejection in the in-service VIRM.

[1-1 VIN and chassis number](#)