

Correct as at 17th May 2026. It may be superseded at any time.

Extract taken from: In-service certification (WoF and CoF) > Heavy PSVs > Vision > PSV demisters

## 5-6 PSV demisters

### Reasons for rejection

#### Mandatory equipment

1. The windscreen **and** side window used by the driver is not equipped with demisting equipment.

#### Condition and performance

2. The demisting equipment:

- a) does not operate, or
- b) is ineffective, eg the air is not hot enough or there is insufficient volume, or
- c) cannot be operated from the driver's seat.

### Summary of legislation

#### Applicable legislation

- [Land Transport Rule: Passenger Service Vehicles 1999](#).

#### Mandatory equipment

1. The front windscreen and side windows used by the driver must be equipped with effective demisting equipment, adjustable from the driver's seat.