

Correct as at 17th May 2026. It may be superseded at any time.

Extract taken from: In-service certification (WoF and CoF) > Heavy PSVs > Vision > Rear-view mirrors

## 5-4 Rear-view mirrors

### Reasons for rejection

#### Mandatory equipment

1. A class MD3, MD4, ME, NB or NC vehicle is not fitted with:
  - a) an outside left-hand rear view mirror, or
  - b) an outside right-hand rear view mirror.
2. An unclassified vehicle is not fitted with at least one rear view mirror.

#### Permitted equipment

3. Refer to [general vehicle pages](#).

#### Condition

4. Refer to [general vehicle pages](#).

#### Performance

5. Refer to [general vehicle pages](#).

## Summary of legislation

### Applicable legislation

- [Land Transport Rule: Windscreen Wipe and Wash, and Mirrors 1999](#).

#### Mandatory equipment

1. A class MD3, MD4, ME, NB and NC vehicle must be fitted with an outside left-hand and an outside right-hand rear-view mirror.
2. An unclassified heavy vehicle must be fitted with at least one rear-view mirror.

#### Permitted equipment

3. Refer to [general vehicle pages](#).

#### Condition

4. Refer to [general vehicle pages](#).

## **Performance**

5. Refer to [general vehicle pages](#).

## **Modification and repair**

6. A rear-view mirror that is affected by a modification or repair:

- a) must meet the requirements for equipment, condition and performance, and
- b) does not require HVS certification.