

New warning label available to order

The new cardan shaft park brake warning label is now available to order via the NZTA/Bluestar portal.

Product code # TA5166



The old design is still acceptable for the purposes of passing a CoF, however we recommend replacing it with the new version wherever possible.

The new label includes a QR code which takes people to the CSPB page on our website – where the updated safety alert and a new video for drivers of vehicles fitted with CSPB is available.

www.nzta.govt.nz/cardanbrakes

Inspection protocol

When inspecting vehicles, please continue to follow the current CSPB testing requirements and procedures. No protocols have changed.

Remember, the certified inspector must apply the brake – not the vehicle's driver.

If you need a refresher:

[New Zealand heavy vehicle brake test protocol](#)

Video guide: [Testing cardan shaft brakes using a roller brake machine](#)