

Correct as at 25th April 2026. It may be superseded at any time.

Extract taken from: Alternative fuel system certification > CNG inspection > Cylinder attachment

2-4 Cylinder attachment

Reason for rejection

Condition

1. The security of the container attachment has been affected or weakened by:
 - a) rust, corrosion, abrasion or impact damage, or
 - b) loose nuts, worn or stretched bolts, or
 - c) loose bands, wear under bands, incompatible band materials, or
 - d) cracks or metal fatigue.

Summary of legislation

Applicable legislation

- AS/NZS 2739: 2003, section 6.9.

Condition

1. A cylinder attachment must not have any of the following conditions such that the security of the attachment is at risk:
 - a) rust, corrosion, abrasion or impact damage
 - b) loose nuts, worn or stretched bolts
 - c) loose bands, wear under bands, incompatible band materials
 - d) cracks or metal fatigue.