

13 December 2017

VIRM: Light vehicle repair certification update – effective 13 December 2017

List of changes

To view the page click on the link in the section column.

To view the changes in one document download the [List of changes and preview pages](#).

Section	Change description
Introduction 3 Inspection and certification process	<ul style="list-style-type: none"> • New instruction on what to do if no LANDATA record is available or if you are unable to key in the NOTES screen.
9-1 Water damage	<ul style="list-style-type: none"> • Note 1 updated – deviations from Table 9-1-1 are no longer considered by the Transport Agency (Summary of legislation 3 also deleted for this reason). • Note 5 updated – if the repair certifier notes that the vehicle has been water damaged but this is not recorded in LANDATA, contact the Transport Agency at FRR@nzta.govt.nz
9-5 Fire damage	<ul style="list-style-type: none"> • Note 1 deleted to make fire damage process more efficient. • Note 5 updated – if the repair certifier notes that the vehicle has been fire damaged but this is not recorded in LANDATA, contact the Transport Agency at FRR@nzta.govt.nz. • Note 6 deleted.