

## 1 March 2018

### VIRM: Entry certification update – effective 1 March 2018

#### List of changes

- To view the page, click on the link in the section column
- To view the changes in one document download the [List of changes and preview pages](#).

Section	Change description
<b>Inspection and certification</b>	
<a href="#">8-1 Service brake and park brake</a>	The latest phase of changes related to electronic stability control (ESC) – used class MA vehicles (passenger cars) with engine capacity greater than 2 litres inspected at the border from <b>1 March 2018</b> must have ESC fitted.