


Correct as at 29th September 2021. It may be superseded at any time.

Extract taken from: NZTA Vehicle Portal > VIRMs > Entry certification > Reference materials > Examples of major structural damage and corrosion > Under body damage: Tearing of the metal

### 71-3 Under body damage: Tearing of the metal

---





Page amended **28 April 2014** (see [amendment details](#)).