

Correct as at 26th June 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of minor non-structural cosmetic damage > Sills/rocker panels (minor damage)

6-2 Sills/rocker panels (minor damage)

Sills/rocker panels (minor damage)





