


Correct as at 10th June 2026. It may be superseded at any time.

Extract taken from: Entry certification > Reference materials > Examples of major structural damage and corrosion > Under body damage: splitting of seam wells

71-2 Under body damage: splitting of seam wells





Page amended 28 April 2014 (see [amendment details](#)).