

Correct as at 25th April 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of major structural damage and corrosion > Under body damage: splitting of seam wells

5-2 Under body damage: splitting of seam wells

Under body damage: splitting of seam wells



