

Correct as at 26th April 2026. It may be superseded at any time.

Extract taken from: Entry certification > Reference materials > Examples of major structural damage and corrosion > Damage to rocker panels and cant rails

71-4 Damage to rocker panels and cant rails














Cant rails





Page amended 1 October 2023 (see [amendment details](#)).