

Correct as at 26th April 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of major structural damage and corrosion > Rear quarter/dogleg

5-5 Rear quarter/dogleg











