

Correct as at 26th April 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of major structural damage and corrosion > Dogleg flag

5-6 Dogleg flag

Look for discrepancies in the door gap.









