

Correct as at 16th May 2026. It may be superseded at any time.

Extract taken from: Entry certification > Reference materials > Examples of major structural damage and corrosion > Dogleg flag

71-6 Dogleg flag

Look for discrepancies in the door gap.











Page amended **28 April 2014** (see [amendment details](#)).