

Correct as at 17th May 2026. It may be superseded at any time.

**Extract taken from:** Border inspection of imported used vehicles > Reference materials > Examples of minor non-structural cosmetic damage

## 6 Examples of minor non-structural cosmetic damage

### 6-1 Front guards

Front guards









## 6-2 Sills/rocker panels (minor damage)

Sills/rocker panels (minor damage)









### **6-3 Minor/cosmetic damage: rear quarter panel and dogleg**

Minor/cosmetic damage: rear quarter panel and dogleg











#### **6-4 Minor/cosmetic damage: floor pan stiffening members**

The minor/cosmetic damage in these images doesn't need to be referred to a repair certifier.





Page added 21 February 2024 (see [amendment details](#))