

Correct as at 6th June 2026. It may be superseded at any time.

Extract taken from: Border inspection of imported used vehicles > Reference materials > Examples of minor non-structural cosmetic damage

6 Examples of minor non-structural cosmetic damage

6-1 Front guards

Front guards









6-2 Sills/rocker panels (minor damage)

Sills/rocker panels (minor damage)









6-3 Minor/cosmetic damage: rear quarter panel and dogleg

Minor/cosmetic damage: rear quarter panel and dogleg











6-4 Minor/cosmetic damage: floor pan stiffening members

The minor/cosmetic damage in these images doesn't need to be referred to a repair certifier.





Page added 21 February 2024 (see [amendment details](#))